

Physical and biological monitoring of STREAM restoration projects Year Four Report

Natural England

August 2009 **Final Report** 9S0459



ACOMPARY OF

HASKONING UK LTD.

ENVIRONMENT

Burns House Harlands Road Haywards Heath, West Sussex RH16 1PG United Kingdom +44 (0)1444 458551 Telephone 0144440665 Fax info@haywards-heath.royalhaskoning.com E-mail www.royalhaskoning.com Internet

Document title	Physical and biological monitoring of STREAM restoration projects Year Four Report
Version	02
Status	Final Report
Date	August 2009
Project name	River Avon STREAM Monitoring
Project number	9S0459
Client	Natural England
Reference	9S0459/R05/JLE/Hayw

Drafted by	Joanna Eyquem	
Checked by	Simon James	
Date/initials check	28 / 08 / 2009	SJ
Approved by	Simon James	
Date/initials approval	28 / 08 / 2009	SJ

ROYAL HASKONING

CONTENTS

1	INTRODUC	CTION	1
	1.1	The STREAM Restoration Project	1
	1.2	Physical and Biological Monitoring	1
	1.3	Reporting format	1
2	METHOD		3
	2.1	Monitoring Protocol	3
	2.2	Changes since the pre-restoration surveys	5
	2.3	Realisation of the Monitoring Protocol	5
3	RAPID ASS	SESSMENT RESULTS	7
	3.1	Amesbury	7
	3.2	Dockens Water	12

APPENDIX A: REACH SCALE MAPPING*

APPENDIX B: PHOTOGRAPHIC RECORDS*

(*All appendices are designed to be inserted into a ringbinder that accompanies this report and will be updated on an annual basis)

ROYAL HASKONING

1 INTRODUCTION

1.1 The STREAM Restoration Project

Demonstrating Strategic Restoration and Management (STREAM) is funded jointly by the European Commission's LIFE-Nature programme, Natural England, Environment Agency, Wiltshire Wildlife Trust, Hampshire and Isle of Wight Wildlife Trust, and Wessex Water to improve river habitat conditions along a number of reaches of the River Avon Special Area of Conservation identified in **Table 1.1** and **Figure 1.1**.

Table 1.1 Location of river restoration sites within the Avon c	atchment
---	----------

Site name	Watercourse	Upstream limit	Downstream limit		
1.1 Upper Woodford	River Avon	SU 13183755	SU 12603723		
1.2 Fovant	River Nadder	SU 00213059	SU 00663072		
1.3 Seven Hatches	River Wylye	SU 09243304	SU 09833178		
1.4 Amesbury	River Avon	SU 15834257	SU 15624195		
1.5 Hale	River Avon	SU 17401889	SU 16351791		
1.6 Blashford	Dockens Water	SU 15410828	SU15300826		

Further details about the project and outline design of the restoration works to be undertaken are contained within the original LIFE bid document (English Nature, 2005).

1.2 Physical and Biological Monitoring

As part of the STREAM project, Royal Haskoning has been commissioned by Natural England to undertake physical and biological monitoring at each of the six restoration sites.

Monitoring will involve one pre-restoration and one post-restoration survey at each site. These surveys will be used to document the restoration works and to identify the possible influence of the works on ecology within the reach. Reach-scale mapping and repeat photography techniques will be used to monitor change at all restoration sites. It is not possible to undertake detailed survey at all sites due to resource constraints and practical limitations. Therefore two of the sites will also be subject to more detailed survey and the use of control sites.

1.3 Reporting format

The findings of the monitoring project will be reported at the end of each of the four years of the project. This document reports on the findings of the forth year's monitoring surveys undertaken in 2009 at the following sites:

Detailed survey

None undertaken this year

Rapid assessment

- Amesbury Restoration Site (AMR);
- Dockens Water Restoration Site (DOR).

Warminster Amesbury Durrington Amesbury Woodfords. Wiltshire Wildlife Trust Centre-Seven Hatches Fovant Salisbury Wilton Downton lale Fordingbridge Dockens Water Hampshire Wildlife Trust Centre Ringwood 17 Potential River Restoration Site Wildlife Trust Education Centres -Major Urban Areas River Avon cSAC River Avon Catchment Christchurch Map Drawi By: Martli Giloirist Date: 13/7.2005 Ref. ⊕ English Nature 2005 Scale 1:750000 ∱ Grid English Nature Wiltshire Team Prince Maurice Court Hambleton Avenue 12 37 500yd North map is based upon Onlinance Survey material with the permission of ance Survey on behalf of the Controller of Ner Makes by Stationery e © Crown copytight, all Rights Reserved, Unsubtatised reproduction yes Crown copytight and may lead to procession or chill cedlings, License Number 1000/17954, 2005 This is Ordination Devizes Wiltshire SN10 2RT

Figure 1.1 Location of STREAM restoration sites within the Avon Catchment

The purpose of this report is to present the data that has been collected this year and summarise any initial findings in relation to the physical and biological characteristics of the sites surveyed.

The primary data is contained within the appendices that accompany this report within a ringbinder. This ringbinder will be updated following subsequent annual reports in order to collate all of the data gathered over the four year period in one place.

2 METHOD

2.1 Monitoring Protocol

The methods used in gathering the physical and biological survey data presented in this report are based on those agreed with Natural England in developing the River Avon STREAM Monitoring Project – Monitoring Protocol (Royal Haskoning, 2006). The monitoring protocol describes how the monitoring sites were selected and the monitoring framework (**Figure 2.1**) together with the rationale underlying the project and should be read in conjunction with this report.

The following statements define the purpose and limitations of the monitoring framework.

- The pre-restoration survey will establish a record of biological and physical conditions at the site prior to restoration.
- The post-restoration survey will record modifications to the channel after restoration.
- The surveys will both provide snapshots pre- and post-restoration. It is important to recognise that there is a limitation to the comparisons that can be made over this short duration and it will not be possible to draw any conclusions regarding changes in conditions at a site pre / post-restoration.
- The relationship between physical and biological conditions will be analysed at each site. Comparisons will be drawn concerning the relationships identified at each site at the time of survey, taking into account other factors and processes that may influence relationships.
- The limitations of the control sites will prevent direct comparison of the restoration reaches with the control sites. The purpose of using the control site is to compare the relationship between physical and biological conditions recorded at both sites on a given day rather than to compare the magnitude of change of either physical or biological parameters between sites. Comparisons will therefore be made between pre-restoration and post-restoration surveys at each individual site. Inference may be drawn about changes in each parameter and in the relationship between physical and biological character.
- This monitoring framework will establish a documented baseline in order that repeat surveys of both physical and biological conditions can be made over longer time periods.



Figure 2.1 Monitoring framework for the Avon STREAM Monitoring Project

2.2 Changes since the pre-restoration surveys

A summary of the restoration works implemented as part of the STREAM project is provided below. More detailed information can be obtained in the bespoke design reports – please contact Natural England to obtain these further details.

Amesbury

The STREAM project carried out works to restore the River Avon at Amesbury in autumn 2008. The aim of the restoration work was to work with natural processes to modify the channel to a more appropriate width, shape and slope, and re-introduce woody debris to vary flow speed and direction, and sediment movement. The restoration work within the monitored reach included:

- selectively felling trees and anchoring them securely in the river as deflectors;
- re-grading part of the bank to make a more gently sloping river bank.

In addition to these works, gravel shoals/shoulders were installed downstream of the monitored reach whilst upstream selected coppicing was undertaken.

Dockens Water

Works were undertaken to complement river restoration that has already been completed at Hampshire and Isle of Wight Blashford Lakes Nature Reserve. The objective of this work was to improve the connection between the river and its floodplain, reduce shading, and restore a more dynamic channel. The work was completed in August 2008 and included:

- forming a small (approximately 15 metres long) floodplain pool connected with the river via a small channel that mimics a natural chute;
- decreasing heavy shading by felling a small number of non-native trees alongside and around the chute;
- creating brushwood barriers between the new path and pool to ensure safe public access to the area.

2.3 Realisation of the Monitoring Protocol

2.3.1 Reach-scale mapping

Reach-scale mapping of all sites was undertaking according to the monitoring protocol using Fluvial Audit, Physical Biotope Mapping, River Corridor Survey and repeat photography. Fluvial Audit sheets, Physical Biotope maps and River Corridor Survey maps have been prepared for each site and are presented in **Appendix A**. Definitions of the physical biotopes that were used during Physical Biotope Mapping are provided in Table 2.1. These definitions are consistent with those used during River Habitat Survey (RHS).

Physical Biotope	Definition
Rapid	Boulder/cobble substrate with stepped profile. Associated with 'white water' from broken
	standing waves
Riffle	Shallow, fast flowing, discrete section of up to 5 channel widths in length. Unconsolidated
	gravel substrate with 'bubbling' unbroken standing waves.
Run	Shallow, fast flowing section, similar in character to a riffle but not a discrete feature.
Boil	Associated with upwelling flow, typically found on the outside of tight meander bends,
	behind structures, d/s of waterfalls
Glide	Section of smooth or rippled flow, deeper flow than a run.
Pool	Sections of deeper flow of up to 3 channel widths in length that are sustained by scour.
	Typically located on the outside of meander bends, downstream from bedrock outcrops
	(plunge pools) and weirs. Does not include impounded sections.
Ponded reach	Sections of no perceptible flow where water is impounded upstream of natural bedrock
	controls and weirs.
Marginal deadwater	Margins of the main channel where there is no perceptible flow.

Table 2.1 Physical biotope definitions

For definitions of other terms used in the Fluvial Audit and River Corridor Survey please refer to the relevant reference sheets within **Appendix A**.

Photographic survey records are contained within Appendix B.

No additional detailed survey techniques were undertaken in 2009.

3 **RAPID ASSESSMENT RESULTS**

3.1 Amesbury

415044 142522 **Upstream limit: Downstream limit:** 415655 142005 Length of site: 654m

Location:

The site is located either side of the A303 dual carriage way to the north of Amesbury. The upstream boundary of the site is parallel to the beginning of the ditch system on the left hand bank. The downstream boundary of the site is where the river branches in two, upstream of a weir structure. The A303 crosses at approximately the mid-point of the site.

Typical photographs:



a) 2006

b) 2009

Photo 3.1.1 - AMR01j: Looking upstream of the road crossing. Large Woody Debris deflectors on the right hand bank in 2009.





Photo 3.1.2 - AMR01k: Looking downstream to road crossing. Large Woody Debris deflectors on the right hand bank in 2009.



a) 2006

b) 2009

Photo 3.1.3 - AMR02e Looking downstream along glide physical biotope downstream of the road crossing. The public footpath is along the left hand bank.



a) 2006

b) 2009

Photo 3.1.4 - AMR02f: Looking upstream. Large Woody Debris deflectors on the right hand bank in 2009.

Comparison with pre-restoration survey (2006)

The restoration works implemented at Amesbury have results in visual differences in the nature of flow and vegetation within the channel and on the floodplain, both upstream and downstream of the A303 road bridge. Upstream of the road bridge felling of poplar trees along the left hand bank (by the landowner) has opened up the floodplain (**Photo 3.1.1a and 3.1.1b**). Large Woody Debris (LWD) deflectors installed on alternate banks have resulted in areas of marginal deadwater and increased vegetation at the channel margins (**Photo 3.1.2a and 3.1.2b**).

Downstream of the A303 road bridge selected felling of trees (by the landowner) within the park has also opened up the floodplain and reduced shading (**Photo 3.1.3a and 3.1.3b**). LWD deflectors have also been installed on alternate banks. These are creating areas of marginal deadwater which are encouraging increased vegetation at the channel margins (**Photo 3.1.4a and 3.1.4b**).



3.1.1 Physical Characteristics

Physical biotopes

The site consists primarily of a glide which is divided in two by the culvert under the A303 dual carriage way (**Map 3.1**). LWD deflectors installed along alternate banks upstream and downstream of the culvert create areas marginal deadwater immediately downstream of the deflectors. In addition, the deflectors divert flow towards the opposite bank within these areas, creating a slightly sinuous flow path throughout the reach. The bed of the culvert is artificial and is acting as a grade control between the two sections.

Comparison with pre-restoration survey (2006)

In 2006, prior to the restoration works, flow was uniform and slow flowing throughout the study reach. Whilst flow remains generally slow flowing, the installation of the LWD deflectors has created some diversity. There are now areas of marginal deadwater and shallower waters on top of the deflectors that can be distinguished from the main flow, thus creating more varied habitat conditions.

Sediment regime

The Fluvial Audit recorded no evidence of natural channel adjustment through erosion (see **Appendix A**). Localised sourcing of fine sediment to the channel is occurring due to poaching by humans and dogs within the land open to public access.

The predominant sediment process within the site is deposition of fine sediment due to the overwide / overdeep nature of the modified channel. Sedimentation is particularly occurring at the channel margins and in the lee of the LWD deflectors due to the creation of areas of marginal deadwater.

Comparison with pre-restoration survey (2006)

Sedimentation is occurring, as in 2006, due to the historically modified nature of the channel. However, due to the presence of the LWD deflectors, sedimentation is more concentrated at the channel margins than on the channel bed along the main flow path. Poaching is continuing to occur within the land open to public access and the area poached has become larger since 2006.

3.1.2 Biological characteristics

In-channel vegetation occurs throughout the channel. Species observed include Unbranched Bur-reed (*Sparganium emersum*), the negative indicator Fennel Pondweed (*Potamogeton pectinatus*) and a patch of Duckweed (*Lemna minor*) immediately upstream of an overhanging tree. However, areas of water-crowfoot (*Ranunculus pencillatus spp.*) were also observed within the reach.

Emergent vegetation is present semi-continuously along the right hand bank. The dominant species are Branched Bur-reed (Sparganium erectum) and Reed Sweet-grass (*Glyceria maxima*), with Greater Pond Sedge (*Carex riparia*) occurring in the downstream section of the site. Stands of emergent vegetation also occur along the left hand bank, in particular upstream of the A303 road bridge. There are also occasional stands of watercress (*Callitriche spp.*) and Water Mint (*Mentha aquatica*). These species are frequently associated with the LWD deflectors. At the downstream end of the reach, a section of marginal fringe has been pushed further into the channel and is well-established, acting to narrow the channel at this location.

The riparian zone along the right hand bank is better established than along the left hand bank with scattered willow trees and alder, and is dominated by ruderal vegetation such as Common Nettle (*Urtica dioica*), with Great Willow Herb (*Epilobium hirsutum*) occurring downstream of the road culvert), Meadowsweet and Great Willow Herb. Along the left hand bank upstream of the road bridge there is a mown grass fisherman's path which limits the width of the riparian zone. On the left hand bank there is a line of Poplars downstream of the road bridge. Species present along both include Common Nettle, Great Willow Herb, with occasional Meadowsweet and hemlock water dropwort (*Oenanthe crocata*).

Landuse along the right hand bank consists of tall grass and ruderal vegetation set back from the channel bank which is bordered by a mown fisherman's path. The downstream section of the site is open to public access and a footpath follows the right bank. On the left hand bank the landuse is tall ruderal vegetation dominated by Common Nettle and Common Comfrey (*Symphytum officinale*).

Comparison with pre-restoration survey (2006)

The dominant species present in the channel and marginal zone remain similar to those observed in the 2006 survey. However, additional species were observed in 2009, including water-crowfoot (*Ranunculus pencillatus spp.*), watercress (*Callitriche spp.*) and Water Mint (*Mentha aquatica*), which are frequently associated with the LWD deflectors. Occurrence of duckweed is less frequent than in 2006, now limited to one location.

The most dramatic difference in vegetation, however, is along the floodplain upstream of the A303 road bridge, where the previous poplar plantation has been felled by the landowner and has been replaced by tall herbs and ruderal vegetation.

3.1.3 Physical and biological relationships

- The cross-sectional profile of the channel has been widened and deepened as a result of historical dredging. This, combined with impoundment upstream of the downstream weir, results in deep, slow flow conditions.
- The depth and flow conditions within the channel are still likely to be limiting the extent and diversity of macrophyte species within the channel.
- Installation of LWD deflects has created some flow diversity within the reach, including areas of marginal deadwater in between and shallower waters on top of the deflectors. Marginal fringe species, such as water mint (*Mentha aquatica*), have established in some of these areas.
- The width of the riparian zone is restricted along the left hand bank due to footpaths used for fishing and public access and poaching is continuing to occur in localised areas.

3.2 Dockens Water

Upstream limit:	415142 108146
Downstream limit:	415513 108293
Length of site:	433m

Location:

The site is located to the south west of Ellingham Harbridge and Ibsley and runs parallel to Ellingham Drove. The upstream boundary of the site is the bridge between the sand and gravel pit and the water treatment works. The downstream boundary of the site is where the track meets Ellingham Drove (Figure 3.2)

Typical photographs:



a) 2007

b) 2009

Photo 3.2.1 - DOR01-c: Looking upstream towards footbridge. Point bar on the inside of meander bend.



a) 2007

b) 2009





a) 2007

b) 2009

Photo 3.2.3 - DOR01-k: One of several fallen trees remains in the same position.



a) 2007

b) 2009

Photo 3.2.4 - DOR01-n: Looking downstream with vegetated bar in the foreground.

Comparison with pre-restoration survey (2007)

There are few visual differences between the photographs taken in 2007 and those in 2009. The main morphological difference is the construction of a pool / backwater on the left hand bank where the channel was previously embanked. In addition, a new footbridge has been constructed downstream of this pool for public access (see **Map 3.2**).

Most morphological features have remained in position since the baseline survey with only minor alterations. Vegetation cover also remains unchanged along the river, although significant works have been undertaken away from the river to improve access within the Blashford Lakes Nature Reserve.



3.2.1 Physical Characteristics

Physical biotopes

The channel is morphologically diverse and characterised by a number of different physical biotopes; glides, riffles, runs and pools were observed in sequence throughout the reach (Figure 3.2).

Comparison with pre-restoration survey (2007)

Physical biotopes throughout the reach remain very similar to those observed during the 2007 baseline survey. Differences are limited to minor changes in bar shape and size and modifications where the enhancement works themselves have been implemented where a new bar has formed and the pool-riffle sequence has been modified by the presence of a fallen tree across the channel and creation of an offtake to the pool feature.

Sediment regime

The dominant bed materials at the site are fine gravel and sand. The bank material varies but is predominantly earth comprising silt and sand which is subject to fluvial scour in places. Flow velocities are locally variable influenced by the irregularly meandering planfrom, though the average reach gradient is low.

Evidence of erosion was found at the upstream limit with both scour and bank erosion occurring on the left hand bank. A number of depositional features were observed throughout the study reach, including point bars and side bars composed of gravels and silts. The majority of the depositional features were unvegetated, indicating temporary storage and potential for transport downstream in periods of increased flow. However some bars have vegetated, forming more permanent and semi-permanent features. Tree roots and fallen trees are also creating temporary silt bars upstream in places.

The planform of the river and confined nature of the channel suggests that the river has been historically realigned. At the upstream end of the site there is evidence of dredging, which appears to have been used to embank the channel at several locations throughout the study reach. The embankments are currently limiting the interaction of the river with the floodplain thus limiting potential for sediment transfer to the floodplain. A fallen bridge near the downstream limit is acting as a local grade control limiting channel bed adjustment at, and upstream of, this location. Upstream of this structure, an offtake to a pool / backwater has been created and the embankment has been locally lowered. The pool was dry at the time of survey but may receive flow during high flow events.

The dominant sediment processes at the site are the transport and localised deposition of sediment occurring as a result of varied flow velocities throughout the reach. Previous modification is limiting the transfer of sediment to the floodplain in high flow conditions.

Comparison with pre-restoration survey (2007)

The sediment regime remains very similar to that observed during the 2007 baseline survey. Differences are limited to minor changes in bar shape and size, most noticeably where the enhancement works themselves have been implemented. Sediment may be transferred into the pool created during high flow events but was not connected with the channel at the time of survey.

3.2.2 Biological characteristics

The site is heavily wooded on both banks with broadleaved trees creating a continuous riparian buffer. In channel vegetation is sparse and dominated by a few mosses and liverworts and there is no emergent vegetation present. This is likely to be due to overshading and the shallow flow conditions in the channel.

Land use on both the right and left hand banks is broadleaved woodland. The dominant species are Pendunculate Oak (*Quercus robur*), Common Beech (*Fagus sylvatica*), Sycamore (*Acer pseudoplatanus*), Holly (*Ilex aquifolium*) and Ash (*Fraxinus excelsior*) many of which overhang and shade the channel. Beneath the woodland, the ground is predominantly covered with leaf litter, with some bare ground, Bracken (*Pteridium aquilinum*), Cranesbill (*Geranium sp.*) and Ivy (*Hedera helix*).

The riparian buffer zone is a continuous but narrow strip on both the left and right banks and is dominated by the Common Nettle. There are public footpaths running either side of the river corridor.

Comparison with pre-restoration survey (2007)

There has been limited significant biological change since the 2007 baseline survey. Selected trees have been removed. However, larger fallen trees remain in the same position and are influencing flow along Dockens Water.

Himalayan balsam (*Impatiens glandulifera*), an invasive non-native species which was previously present on both banks was not observed during the 2009 survey and is likely to have been removed by the Hampshire and Isle of Wight Wildlife Trust who maintain the Blashford Lakes Nature Reserve.

3.2.3 Physical and biological relationships

- The channel is morphologically diverse displaying both erosional and depositional features.
- The channel is disconnected from the floodplain due to previous channel modifications, including dredging and embankment.
- A pool / backwater has been created by locally lowering the embankment on the left hand bank and excavating a depression. However, there was no water in the pool at the time of survey.
- There is little in-channel or riparian vegetation likely to be due to overshading of the channel by woodland. Shallow water depths are also likely to be limiting emergent vegetation.

Appendix A: Reach-Scale Mapping



Part I: SURVEY CONDITIONS

See n	eleva	nt 1:2	25000	mapping ar	nd watercourse si	ummary sheet for	watercourse nam	e and Reac	h ID code	STATISTICS STATISTICS	NO. THE REAL PROPERTY AND	Contraction of
Catchment Wat		Water	course	Reach ID	Reach ID		NGR Start 415844 142522		Surveyor			
		201			River An	von	AMR-	-01	NGR End	415872	142156	are
Date	14	17	109	Time	11.25	Flow (tick):		Low/base		Above low		High
Conditions influencing survey quality:				ility:		Reason for ups				NGR (GPS) map	No. of Photos	

Part II: SEDIMENT SOURCES

Point Sources							
	Fine	Coarse	Totals		Fine	Coarse	Totals
Tributaries*				Scour at structure			1
Field drain/mill leat*				Tree fall			-
Tipped Material*				Footpath			
Collapsed building/wall*				Burrowing			
Vehicle access				Poaching			
Outfalls				Fishing platforms			
Diffuse Sources							
Fluvial erosion	Micro	Meso	Macro	Geotechnical failure	Micro	Meso	Macro
	Micro	Meso	Macro	Geotechnical failure Toe undermining	Micro	Meso	Macro
Toe scour	Micro	Meso	Macro		Micro	Meso	Macro
Toe scour	Micro	Meso	Macro	Toe undermining Translational	Micro	Meso	Macro
Toe scour Eroding cliff	Micro	Meso Meso	Macro Macro	Toe undermining	Micro	Meso	Macro
Fluvial erosion Toe scour Eroding cliff Hillslope supply direct				Toe undermining Translational Rotational slip	Micro	Meso	Macro

Part III: SEDIMENT TRANSPORT

Morphological F	orms			denie Statistic	
	Tally	Total		Tally	Total
Waterfall			Boil		
Chute			Glide	1	1 .
Rapid			Pool	-	
Riffle			Ponded reach		
Run			Marginal deadwater	LII	8

Part IV: SEDIMENT SINKS

	sourcer source.	s, place totals	s in final box (e.	g. F2, C4)					
Point Sinks					Ad-hoc Fi	sheries Improv	ements		
	Fine	Coarse	Totals			0.28	Tally		Totals
Weirs*					Dredged p	ools			
Dams					Submerge	d vanes			
Fords					Boulder pl	acement			
Bridge			1		Deflectors			· · · · · · · · · · · · · · · · · · ·	
Large woody debris					Minor weir	8			
					Vegetation	n management			
Diffuse Sinks		Recent floo	od chaos?	۵	Yes	R.	No		
	Permanent			Semi-perm	anent	anent		Temporary	
	Micro	Meso	Macro	Micro	Meso	Macro	Micro	Meso	Macro
Floodplain deposits									
Splays		1							
					and the second				
Channel Deposits									
	ent, semi-perma	nent and tem	porary sedimer	t deposits M	cro = <10m ²	, Meso = 10-15	0m². Macro	= < 150m ²	
Tally and total perman							0m², Macro	= < 150m ²	
Tally and total perman		E on right of			not tally isola				
Tally and total perman	present, place an	E on right of		e (>33%) - do	not tally isola		0m², Macro Tempora IMicro	ary	Macro
Tally and total perman Tick types of storage p	Permanent	E on right of	box if extensiv	e (>33%) - do Semi-perm	not tally isola anent	ated boulders	Tempora		Macro
Channel Deposits Tally and total perman Tick types of storage p Boulder/cobble Cobble/gravel	Permanent	E on right of	box if extensiv	e (>33%) - do Semi-perm	not tally isola anent	ated boulders	Tempora	ary	Macro
Tally and total perman Tick types of storage p Boulder/cobble	Permanent	E on right of	box if extensiv	e (>33%) - do Semi-perm	not tally isola anent	ated boulders	Tempora	ary	Macro
Tally and total perman Tick types of storage p Boulder/cobble Cobble/gravel Fine material	Permanent	E on right of	Macro	e (>33%) - do Semi-perm	not tally isola anent	ated boulders	Tempora Micro	Ary Meso	
Tally and total perman Tick types of storage p Boulder/cobble Cobble/gravel	Permanent Micro	Meso	Macro	e (>33%) - do Semi-perm Micro	not tally isola anent Meso	Macro	Tempora	ary	

Part V: VALLEY Landuse codes:	OVERVIEW	1	mondle of Mar	dland (RI) Co	ruh (SH) Wet	land (WL), Moo	rland Heath	(MH), Grazing (G),	
Landuse codes: Tilled land (TL).	Coniferous Woo	(SW) Road/T	rack (RT) Su	burban/urban i	(SU), Recreati	onal (RE)	allhert		and the second sec	1. A.
Tilled land (TL).	Standing water	(SVV), Roau/I	Landuse (do	minant type)		Floodplain (tic	k one)	Width (tick one)	
Valley Form (tio	Shallow Vee		Lunddoo (uu	5m	50m			LH RH	0	12
	Deep Vee		LH [1 0	None		< 1 river width	
	Gorge			RE	TH		One bank		1-5 river widths	
-	Concave/Bowl		RH	C 14	SH		Alternate		5-10 river width	
	Terraced valley	floor		SM	511		Both banks		> 10 river width	s
-	Not visible									
Riparian Buffe		e)	1	Nidth of strip (tick one)			Bank top vege)
LH	RH			LH	RH			LH	RH	form
		None				None		Ø		iform
		Indefinite				< 1 river width				nple
		Fragmentary				1-5 river width:				mplex seased alders?
		Continuous				> 5 river width	S		1777 C 1777 C	vasive species?
-									Trashlines (tick	
Connectivity		Terraces (tick	one)	Insert no.	LH -	Levees (tick if		1		
•				of terraces	RH —	Ш	RH	Name		
Channel discor	nnected from	LH	RH			D/	Ø	None	land and a start	
floodplain?		0		None					If Yes:	Estimate
(no out of bank	flow)			Indefinite				Man Made	-	height (m)
8	Yes			Fragmentary				Continuous		neight (m)
	No			Continuous				Fragmented		
Other features	s (e.g. palaeoc	hannels)								
									in a ware	and the second states and
Port VIII CLIAN	INEL GEOMET	RY								
			Cross-secti	on (tick one)		Channel Dim	ensions			
Planform (tic)				Rectangular/		Width	Depth	Symmetry	(tick one)	
	Straight			U-shaped			E		Uniform	
	Sinuous	dara		Two stage					Variable with	planform
	Irregular mean			Multi-stage				•	Variable witho	ut planform
	Regular mean	ders		Mon stage						
	Braided			Resectioned	Ring Y/N	15	1.8		Qbf Min	Estimate (m)
	Anastomosed	Ring Y/N		Culverted?	Ring Y/N	20	2.2		Qbf Max	
×®	Realigned?	Rung T/IV	32.	Est. length of	The second s	17	2	7	Qbf Mean	
			34	Lot longer of						
O	(tick one)		High		Velocity	(tick one)	BAC	Uniform		
Gradient (use look back	(tick one)		Medium					Varied		
(Use look back	k lest)		Low					Highly varied		
Part VII: BOU	INDARY COND	ITIONS		1						
BED							E if > 33%)			
Bed Material	(tick all prese					all applicable,	E II - 33 /8)	Unsorted		
VE	Obscured		Cobble	Sorting:		Sorted		Natural		/an made
	Fine material		Boulder	Debris:		None		Sub-angular		Rounded
C	Fine gravel	<u> </u>	Bedrock	Sphericity:		Angular		Imbricated		rmoured
	Coarse grave	1 12	Artificial	Imbrication:		None		Non-uniform	_	
	súe			Diversity:		Uniform	₩.	Non-unitorm		
				<u> </u>			Filamentou			
Channel Veg				in-channel ve				n/liverworts		
% cover	15			ating vegetatio				ree roots	JD)	
		<u> </u>	Emergent i	eeds/sedges/r	usnes	2			<u> </u>	<u></u>
BANKS				Drofile (ilal)	if present, E if	> 33%)	Tree lining	(tick one for ea	ch bank)	
Bank materia	Il (tick if present	, E it > 33%)			RH	- 55 /0]	LH	RH	····,	
LH	RH					Cliff/Vertical			None	
D'E	-	Obscured				Stepped			Isolated/scat	tered
		Clay				Graded			Reg. spaced	
		Silt		e	M	Graueu			Occasional o	
E E		Sand				E if > 220/)			Semi-continu	
		Fine gravel		1	tick if present,				Continuous	
		Coarse gra	vel			None	YM		Recent tree	planting
		Cobble				Toe		vegetation (tick	and the second	
		Boulder			inter I	Full	Bank face		RH	
		Bedrock				Walled		LH		None
		Artificial				Concrete				Uniform
	-					Wooden			· •	Simple
(ŶN	Ø∾	Cohesive?				Rip rap				Complex
	\sim					Other				

			and the set form	untersource name and Do	ach ID code			R
See relevant 1:25000 m Catchment	Watercour	se	ton	Reach ID	NGR Start	415872	142156	Surveyor
Date 14/7/09	Time		Flow (tick):	Low/bas	se C	Above low		High
Conditions influencing s			LHB 12 RHB D	Reason for upstream rea	ich boundary:	Record photo and mark on		No. of Photos
Diffuse sources: tally wi	diment sourc	es, place totals nd C for coarse	in final box (e.g. under Micro, M	F2, C4). * = Take GIS re leso or Macro and direct fr	ading and man om slope or inc	k on map lirect e.g.throug	h creep	
Point Sources	Fine	Coarse	Totals			Fine	Coarse	Totals
Tributaries*				Scour at st	ructure			
Field drain/mill leat*				Tree fall				
				Footpath			1	
Tipped Material*								
				Burrowing				-
Collapsed building/wall*				Poaching				3
Collapsed building/wall* Vehicle access					forms			3
Collapsed building/wall* Vehicle access Outfalls				Poaching	forms	<u>111</u>		3
Collapsed building/wall* Vehicle access Outfalls Diffuse Sources	Micro	Meso	Macro	Poaching		Micro	Meso	3 Macro
Collapsed building/wall* Vehicle access Outfalls Diffuse Sources		Meso	Macro	Poaching Fishing plat	al failure		Meso	I
Tipped Material* Collapsed building/wall* Vehicle access Outfalls Diffuse Sources Fluvial erosion Toe scour Eroding cliff		Meso	Macro	Poaching Fishing plat	al failure nining al		Meso	I

direct indirect

Part III: SEDIMENT TRANSPORT

Morphological F	orms				
· · · · ·	Tally	Total		Tally	Total
Waterfall			Boil		
Chute			Glide	1	1
Rapid			Pool		
Riffle			Ponded reach	1	1
Run			Marginal deadwater	11	2

Channel weathering

Part IV: SEDIMENT SINKS

Point Sinks Fine Coarse Totals Totals Weirs* 1	Tally fine and coarse s	ediment source	es, place totals	s in final box (e.	g. F2, C4)				A STATE	
Weirs* Image Image <t< td=""><td>Point Sinks</td><td></td><td></td><td></td><td></td><td>Ad-hoc F</td><td>isheries Improv</td><td>ements</td><td></td><td>1897 - 28 - 28</td></t<>	Point Sinks					Ad-hoc F	isheries Improv	ements		1897 - 28 - 28
Dams	ne talenne of ellevine :	Fine	Coarse	Totals		1 		Tally		Totals
Fords	Weirs*	1		1		Contraction of the second second				
Bridge Large woody debris	Dams					Submerge	ed vanes			
Large woody debris Image: Sinkge in the second	Fords					Boulder p	lacement			
Large woody debris	Bridge					Deflectors	\$			
Diffuse Sinks Recent flood chaos? Yes No Permanent Semi-permanent Temporary Micro Meso Macro Micro Meso Macro Splays Image: Channel Deposits Image: Channel Deposits Image: Channel Deposits Image: Channel Deposits Tally and total permanent, semi-permanent and temporary sediment deposits Micro = <10m², Meso = 10-150m², Macro = <150m²	Large woody debris					Minor wei	r			
Permanent Semi-permanent Temporary Micro Meso Macro Micro Meso Macro Floodplain deposits Image: Channel Deposits Image: Channel Deposits Image: Channel Deposits Image: Channel Deposits Tally and total permanent, semi-permanent and temporary sediment deposits Micro = <10m², Meso = 10-150m², Macro = < 150m²	•••••		5100		_	Vegetation	n management			
Permanent Semi-permanent Temporary Micro Meso Macro Micro Meso Macro Floodplain deposits Image: Channel Deposits Image: Channel Deposits Image: Channel Deposits Image: Channel Deposits Tally and total permanent, semi-permanent and temporary sediment deposits Micro = <10m², Meso = 10-150m², Macro = < 150m²							57*			
Micro Meso Macro Macro Micro Meso Macro Ma	Diffuse Sinks		Recent flor	od chaos?		Yes		No		
Micro Meso Macro Macro Micro Meso Macro Ma										
Floodplain deposits Interior Interior <td></td> <td>Permanent</td> <td>ι</td> <td></td> <td>Semi-perm</td> <td>nanent</td> <td></td> <td>Temporar</td> <td>У</td> <td></td>		Permanent	ι		Semi-perm	nanent		Temporar	У	
Splays		Micro	Meso	Macro	Micro	Meso	Macro	Micro	Meso	Macro
Channel Deposits Taily and total permanent, semi-permanent and temporary sediment deposits Micro = <10m², Meso = 10-150m², Macro = <150m² Tick types of storage present, place an E on right of box if extensive (>33%) - do not tally isolated boulders Permanent Temporary Micro Meso Macro Colspan="2">Mid channel bar Berms Isolated boulders Type of Storage Image: Mid channel bar Mature Islands	Floodplain deposits									
Channel Deposits Taily and total permanent, semi-permanent and temporary sediment deposits Micro = <10m², Meso = 10-150m², Macro = <150m² Tick types of storage present, place an E on right of box if extensive (>33%) - do not tally isolated boulders Permanent Temporary Micro Meso Macro Colspan="2">Mid channel bar Berms Isolated boulders Type of Storage Image: Mid channel bar Mature Islands	Splays									
Tally and total permanent, semi-permanent and temporary sediment deposits Micro = <10m ² , Meso = 10-150m ² , Macro = <150m ² Tick types of storage present, place an E on right of box if extensive (>33%) - do not tally isolated boulders Permanent Temporary Micro Meso Macro Micro Meso Macro Micro Meso Macro Micro Meso Macro Macro Boulder/cobble Image: Semi-permanent Temporary Cobble/gravel Fine material Image: Semi-permanent Temporary Type of Storage Image: Mid channel bar Berms Isolated boulders Image: Side bars Image:										
Tick types of storage present, place an E on right of box if extensive (>33%) - do not tally isolated boulders Permanent Temporary Permanent Micro Meso Macro Micro Meso Macro Boulder/cobble	Channel Deposits									
Permanent Temporary Micro Meso Macro Micro Meso Macro Boulder/cobble Image: Semi-permanent Image: Semi-permanent Temporary Cobble/gravel Image: Semi-permanent Image: Semi-permanent Temporary Fine material Image: Semi-permanent Image: Semi-permanent Image: Semi-permanent Type of Storage Image: Mid channel bar Image: Semi-permanent Image: Semi-permanent Image: Side bars Image: Semi-permanent Image: Semi-permanent Image: Semi-permanent	Tally and total permane	ent, semi-perm	anent and tem	porary sedimer	nt deposits M	icro = <10m ⁺	, Meso = 10-150	0m ² , Macro	= < 150m*	
Permanent Temporary Micro Meso Macro Micro Meso Macro Boulder/cobble Image: Semi-permanent Image: Semi-permanent Temporary Cobble/gravel Image: Semi-permanent Image: Semi-permanent Temporary Fine material Image: Semi-permanent Image: Semi-permanent Image: Semi-permanent Type of Storage Image: Mid channel bar Image: Semi-permanent Image: Semi-permanent Image: Side bars Image: Semi-permanent Image: Semi-permanent Image: Semi-permanent	Tick types of storage p	resent, place a	n E on right of	f box if extensiv	re (>33%) - do	not tally iso	lated boulders			and the second second
Boulder/cobble Middlo Middlo Middlo Middlo Middlo Boulder/cobble Image Image Image Image Image Image Cobble/gravel Image Image Image Image Image Image Fine material Image Image Image Image Image Image Type of Storage Image Image Image Image Image Image Side bars Image Image Image Image Image Image										
Cobble/gravel		Micro	Meso	Macro	Micro	Meso	Macro	Micro	Meso	Macro
Fine material Image: Constraint of the second sec	Boulder/cobble									
Type of Storage Image: Mid channel bar Image: Berms Image: Image: Image: Side bars Image: Side bars Image: Mature Islands	Cobble/gravel									
□ Side bars □ Mature Islands	Fine material									
□ Side bars □ Mature Islands										
	Type of Storage		Mid chann	el bar		Berms			Isolated b	oulders
Point bars For accumulation			Side bars			 Mature Isl 	lands			
			Point bars		D.	Toe accur	mmulation			

Part V: VALLEY OVERVIEW

 Kalendari (Kalendari (Kale Kalendari (Kalendari (Kale	es:Coniferous W			TANGENING STREAM STREAM	LENGT STREET, SOUTH STREET, ST	Construction of the second	loorland Heath	(MH), Grazin	g (G),	
	L), Standing wate	er (SW), Road/	The second se		and the second se	The second se	Alak anal			CENTRE PARTICIPATION
Valley Form			Landuse (dominant type)		Floodplain	(tick one)	Width (tick o		
	Shallow Vee			5m	50m		Marrie	LH RH		
	Deep Vee		LH	RE	BL		None One heat		< 1 river wid	
	Gorge Concave/Bowl		PH				One bank		1-5 river wid	
			RH	SH	SH		Alternate Bath backs		5-10 river w	
	Terraced valle Not visible	y noor			511	- *	Both banks		> 10 river w	ิตเกร
	fer Strip (tick o	ne)	1	Width of strip	(tick one)	1		Bank ten un	notation (liek	200
LH	RH								getation (tick o	ine)
		None			RH	None		LH	RH	Uniform
~		Indefinite				None < 1 river wid	th			Simple
Ū		Fragmentary				< 1 river wid 1-5 river wid				Complex
		Continuous				 5 river wid 5 river wid 				Diseased alders?
		Continuous				~ 5 river wid	015			Invasive species?
Connectivity		Terraces (tick	(one)	Insert no.	LH	Levees (tick	if present)	U	Trashlines (where the second s
connectivity		Terraces (lick	(one)	of terraces	RH -	LEVEES (IICK	RH			LH
Channel disco	onnected from	LH _	RH .	en terrated			2	None		RH
floodplain?		DR I	Ver	None				Natural	If Yes:	EM D
(no out of ban	k flow)			Indefinite				Man Made		Estimate
	Yes			Fragmentary				Continuous	-	height (m)
	No			Continuous				Fragmented		neight (m)
	es (e.g. palaeoc		U	oonunuous		J	<u> </u>	ragmented	1	
		,								
Dert M. OUT					1. A. 20					
	NNEL GEOMET	ĸĭ	0			lot				
Planform (tic				tion (tick one)		Channel Dir				
	Straight			Rectangular/T	rapezoidal	Width	Depth	Symmetry	(tick one)	
1	Sinuous		V	U-shaped					Uniform	8 S
	Irregular mean	n en en anna anna anna anna anna anna a		Two stage					Variable with	
	Regular means	iers		Multi-stage					Variable with	nout planform
	Braided							_		
	Anastomosed		()N	Resectioned?	USE CONTRACTOR CONTRACTOR	15	1.8		Qbf Min	Estimate (m)
YN	Realigned?	Ring Y/N	YN	Culverted?	Ring Y/N	20	2.2	1	Qbf Max	
				Est. length of e	culvert (m)	17	2]	Qbf Mean	
				Distance i Citaran (Bilata)		I.,	-18			
Gradient	(tick one)		High		Velocity	(tick one)	Mark Contraction	Uniform (+ deader	ພະງ
(use look back	k test)		Medium					Varied Highly varied		
			Low				Ц	Highly varied		
Part VII: BOU	NDARY CONDI	TIONS								
BED										
	(tick all present	t, E if > 33%)		Bed Characte	ristics: (tick a	all applicable,	E if > 33%)			
∎∕E.	Obscured		Cobble	Sorting:		Sorted	9	Unsorted		
	Fine material		Boulder	Debris:		None		Natural		Man made
	Fine gravel		Bedrock	Sphericity:	v 🗆	Angular		Sub-angular		Rounded
	Coarse gravel		Artificial	Imbrication:	VV D	None		Imbricated		Armoured
VE	SJE			Diversity:		Uniform		Non-uniform		
- 1-	• •									
Channel Veg	etation:	•	-	in-channel vege	etation		Filamentous	algae		
% cover	10			ting vegetation			Moss/lichen/l			
			Emergent re	eds/sedges/rus	hes	⊽∕	Exposed tree	roots CL	~0)	
BANKS										
	(tick if present, E	E if > 33%)		Profile (tick if p		33%)	-	ck one for eac	h bank)	
	RH			LH	RH		LH	RH		
e e	- 0/E	Obscured		⊡∕E	₽∕E	Cliff/Vertical			None	
		Clay				Stepped	12/		Isolated/scat	tered
9	5	Silt				Graded			Reg. spaced	/singular
	C	Sand							Occasional c	lumps
		Fine gravel		Protection (tick	if present, E i	f > 33%)			Semi-continu	
		Coarse gravel		N		None			Continuous	
		Cobble				Тое	N	N.	Recent tree p	lanting
		Boulder				Full		getation (tick o		
		Bedrock				Walled		LH	RH	
		Artificial				Concrete				lone
_	_					Wooden				Jniform
	(Y)N	Cohesive?				Rip rap		1		Simple
1 22	1.121			1		• •	1			
$\mathbf{\circ}$	•					Other				Complex

R02



ROYAL HASKONING



Part I: SURVEY C	UNDITIONS							R02
See relevant 1:25	000 mapping and	d watercourse sur	nmary sheet for w	vatercourse name and Re	ach ID code		A Starting Starting	
Catchment	Waterc		wer	Reach ID DOR-01	NGR Start NGR End	415142	108146	Surveyor
Date 14 /1	OR Time	16.25	Flow (tick):	Low/bas	se	Above low		High
Conditions influen		ity:	LHB 🗹 RHB 🗆	Reason for upstream rea		Record photo and mark on	o NGR (GPS) map	No. of Photos
Part II: SEDIMEN	T SOURCES							
the provide the second second second second		AND THE REAL PROPERTY OF THE PROPERTY OF	The second s	F2, C4). *= Take GIS re aso or Macro and direct fr	CONTRACTOR OF CONTRACTOR OF CONTRACTOR	CONTRACTOR AND CARDS CONTRACTOR	th creep	
Point Sources								
	Fine	Coarse	Totals		-1.0.1 	Fine	Coarse	Totals
Tributaries*				Scour at str	ucture	1		

Tributaries*				Scour at structure			
Field drain/mill leat*				Tree fall			
Tipped Material*				Footpath			
Collapsed building/wall*				Burrowing			
Vehicle access				Poaching			
Outfalls				Fishing platforms			
Diffuse Sources							
Thursday and in a		1	1.4	Casta shainal failura			
riuviai erosion	Micro	Meso	Macro	Geotechnical failure	Micro	Meso	Macro
Toe scour	Micro	Meso	Macro	Toe undermining	Micro	Meso	Macro
Toe scour		Meso	Macro		Micro	Meso	Macro
Toe scour	Micro 1	Meso	Macro	Toe undermining	Micro	Meso	Macro
Fluvial erosion Toe scour Eroding cliff Hillslope supply	Micro	Meso	Macro	Toe undermining Translational		Meso	
Toe scour Eroding cliff Hillslope supply	1			Toe undermining Translational Rotational slip Complex failure	Micro	Meso	
Toe scour Eroding cliff	Nicro			Toe undermining Translational Rotational slip		Meso	

Part III: SEDIMENT TRANSPORT

Morphological F	orms				
-	Tally	Total		Tally	Total
Waterfall			Boil		
Chute			Glide	1111	5
Rapid			Pool	HITHIT	10
Riffle	HIT HIT I	11	Ponded reach		
Run	HHT I	6	Marginal deadwater		

Part IV: SEDIMENT SINKS

Tally fine and coarse	sediment source	s, place totals	s in final box (e.g	. F2, C4)				A DAY CAR	
Point Sinks			~~~		Ad-hoc F	isheries Improv	/ements		
Second Second	Fine	Coarse	Totals	_			Tally		Totals
Weirs*					Dredged p	pools			
Dams					Submerge				
Fords					Boulder p				
Bridge		1	1		Deflectors				
Large woody debris	11	L.	1		Minor wei	r			
					Vegetatio	n management			
Diffuse Sinks		Recent floo	od chaos?		Yes		No		
	Permanent			Semi-pern	anent		Temporary		
	Micro	Meso	Macro	Micro	Meso	Macro	Micro	Meso	Macro
Floodplain deposits									
Splays				-					
Channel Deposits									
Tally and total perman	ent, semi-perma	anent and tem	porary sediment	deposits M	icro = <10m [·]	² , Meso = 10-15	0m², Macro =	= < 150m ²	
Tick types of storage	present, place ar	n E on right of	box if extensive	(>33%) - do	not tally iso.	lated boulders		Self-restriction of	
	Permanen	t		Semi-perm	nanent		Temporar	У	
	Micro	Meso	Macro	Micro	Meso	Macro	Micro	Meso	Macro
Boulder/cobble									
Cobble/gravel		1		1	1		HTT1	111	
Fine material							1		
Type of Storage		Mid channe	el bar		Berms			Isolated b	oulders
		Side bars			Mature Isl	ands			
	R	Point bars			Toe accur	nmulation			

Part V: VALLEY OVERVIEW

Landuse coo	les:Coniferous W	loodland (CW)	Broadleaf	Noodland (BL),	Scrub (SH), W	etland (WL),	Moorland Heat	h (MH), Grazir	ng (G),	
Valley Form	TL). Standing wat	ter (SW), Road						A AND AND	· · · · · · · · · · · · · · · · · · ·	
	Shallow Vee		Landuse	(dominant type	•	Floodplair	n (tick one)	Width (tick of		
				5m	50m			LH RH		
	Deep Vee		LH	BL	BL		None		< 1 river v	
	Gorge				-		One bank			
111-111-1	Concave/Bow		RH	BL	BL		Alternate		5-10 river	widths
	Terraced valle	y floor		0-	0L	_ ₽ ∕	Both banks		> 10 river	widths
	Not visible ffer Strip (tick o									
LH		ne)		Width of strip				Bank top ve	-	k one)
	RH	N		LH	RH	2001 - C. C.		LH	RH	
		None				None				Uniform
		Indefinite				< 1 river wi			y	Simple
		Fragmentary			9	1-5 river wi				Complex
. UP		Continuous				> 5 river wi	dths			Diseased alders?
Connectivity		Tarrada (lia)				1				Invasive species?
Connectivity	<i>(</i>	Terraces (ticl	(one)	Insert no.			k if present)			s (tick one)
Chappel disc	onnected from	1		of terraces	RH -	LH	RH	12221-1-1-1		LH
floodplain?	onnected from		RH					None		RH
	al fand			None				Natural	If Yes:	
(no out of bar	ik now)			Indefinite		8		Man Made		Estimate
	Yes Com			Fragmentary				Continuous		height (m)
	140	U		Continuous				Fragmented		
	es (e.g. palaeoc									
	aduplain	6001 G	on L	MB.						
Part VI: CHA	NNEL GEOMET	RY								
Planform (tic			Cross-sec	tion (tick one)		Channel Di	manalana			
	Straight			~~ 승규는 ~ 것 ~ ~ ~ 것 것 ~ 것	rananaidal			a		
	Sinuous			Rectangular/T	rapezoidai	Width	Depth	Symmetry	(tick one)	
10	Irregular mean	dara		U-shaped					Uniform	
				Two stage		V				rith planform
	Regular meand	lers		Multi-stage					Variable w	ithout planform
	Braided		0.					7		
	Anastomosed		(M)	Resectioned?	Ring Y/N	4	0.5	1	Qbf Min	Estimate (m)
\otimes	Realigned?	Ring Y/N	YO	Culverted?	Ring Y/N	7	1	4	Qbf Max	
	in places	1.12		Est. length of a	culvert (m)	5.5	0.7		Qbf Mean	
Gradient	(tick one)	D	High		Velocity	(tick one)		11-16-		
(use look bacl	1950 - E - E - E - E - E - E - E - E - E -		Medium		velocity	(tick one)		Uniform		
	(lost)		Low					Varied Highly varied		4
							U	riigiliy valieu		
BED	NDART CONDI									
	(tick all present	. E if > 33%)		Bed Characte	ristics: (tick a	ll annlicable	F if > 33%)			
	Obscured		Cobble	Sorting:		Sorted		Unsorted		
	Fine material		Boulder	Debris:		None		Natural	_	Manusada
V E	Fine gravel		Bedrock	Sphericity:		Angular	0/E	Sub-angular		Man made
	Coarse gravel	-	Artificial	Imbrication:		None		Imbricated		Rounded
$\overline{\checkmark}$	Sand	-	-\.	Diversity:		Uniform				Armoured
i v	sue		Widge)	Diversity.		Unitorni	er.	Non-uniform		
Channel Vege	etation:			in-channel vege	tation		Filamentous	algae		
% cover				ting vegetation	lation		Moss/lichen/li			
				eds/sedges/rus	hes	₽́€	Exposed tree			
BANKS								10013	·····	
Bank material	(tick if present, E	if > 33%)		Profile (tick if pr	resent, E if > 3	3%)	Tree lining (tid	ck one for eac	h hank)	
LH	RH			LH	RH		LH	RH	u sunny	
•		Obscured		a l		Cliff/Vertical			None	
		Clay				Stepped			Isolated/sca	uttorod
₽∕		Silt			_	Graded			Reg. space	
N S	-	Sand							Occasional	
	- /	Fine gravel		Protection (tick	if present F if	> 33%)			Semi-contin	
		Coarse gravel				None			Continuous	
		Cobble				Toe	Y	-	Recent tree	planting
		Boulder			/	-ull	Bank face veg			
		Bedrock				Nalled	Canine indice veg		RH	uarik)
		Artificial			,	Concrete				Mana
_	_ ,			- whe		Vooden				None
(YN		Cohesive?				Rip rap			-	Uniform
						Other				Simple Complex
								-	<u> </u>	COMPICA

R02



Appendix B: Photographic Records

Date	Site	Geomorphological Reach		Photo Reference	Easting	Northing	Orientation	Time	Direction	Height (m)	Description / Comments
24/08/2006	Amesbury	AMR01	n/a	AMR01a	415855	142565	336	11.25	Upstream		Upstream of restoration site. Submerged vegetation in foreground.
24/08/2006	Amesbury	AMR01	n/a	AMR01b	415855	142565	209	11.26	Downstream		Downstream sinuous platform.
24/08/2006	Amesbury	AMR01	n/a	AMR01c	415845	142507	350	11.34	Upstream		Upstream to top of reach.
24/08/2006	Amesbury	AMR01	n/a	AMR01d	415845	142507	282	11.36	Right hand bank		Across channel. Turbid water & submerged vegetation.
24/08/2006	Amesbury	AMR01	n/a	AMR01e	415845	142507	201	11.37	Downstream		Downstream towards meander bend.
24/08/2006	Amesbury	AMR01	n/a	AMR01f	415855	142396	338	11.53	Upstream		Upstream- emergent change on right hand bank. Mown on right hand bank rather then wooded.
24/08/2006	Amesbury	AMR01	n/a	AMR01g	415855	142396	262	11.53	Right hand bank		Across channel. Just upstream of willow tree.
24/08/2006	Amesbury	AMR01	n/a	AMR01h	415855	142396	188	11.53	Downstream		Downstream towards road bridge.
24/08/2006	Amesbury	AMR01	n/a	AMR01i	415862	142374	306	12.12	Upstream Bed		Bed of channel- submeded vegetation & algae.
24/08/2006	Amesbury	AMR01	n/a	AMR01j	415877	142289	339	12.12	Upstream		Upstream along straight section.
24/08/2006	Amesbury	AMR01	n/a	AMR01k	415877	142289	196	12.23	Downstream		Downstream to road bridge. By alder tree.
24/08/2006	Amesbury	AMR01	n/a	AMR01I	415887	142205	196	12.29	Downstream		Downstream to road bridge. By alder tree. Downstream to culvert. Submerged/floating veg along to narrow the channel.
24/08/2006	Amesbury	AMR01	n/a	AMR01m	415978	142240	264	12.23	Downstream		Culvert under road in 32m long.
24/08/2006	Amesbury	AMR02	n/a	AMR02a	415876	142131	354	12.55	Upstream		Upstream towards culvert. Submerged veg difference under culvert.
24/08/2006	Amesbury	AMR02	n/a	AMR02b	415876	142131	224	12.55	Downstream		Downstream around meander bend.
24/08/2008	Amesbury	AMR02	n/a	AMR02b2	415878	142131	224	12.56	Downstream		
24/08/2006	Amesbury	AMR02	n/a	AMR0202	415877	142125	4	13.01	Upstream		Poaching due to public access on right hand bank.
24/08/2006	Amesbury	AMR02	n/a	AMR02d	415853	142137	20	13.08	Upstream		Wide glide through meander.
24/08/2006	Amesbury	AMR02	n/a	AMR020	415853	142076	272	13.14	Downstream		0 0
	,	AMR02		AMR02e AMR02f	415855	142076	42	13.17			Downstream submerged vegetation.
24/08/2006	Amesbury	AMR02 AMR02	n/a				42 346		Upstream		Upstream around meander.
24/08/2006	Amesbury	AMR02 AMR02	n/a	AMR02g AMR02h	415775	142075		13.29 13.30	Right hand bank		Across channel. Unbranched burreed.
24/08/2006 24/08/2006	Amesbury	AMR02 AMR02	n/a n/a	AMR02n AMR02i	415775 415659	142075 142020	271 306	13.30	Downstream		Downstream to weir at right hand bank branch.
	Amesbury			-					Downstream		Weir downstream causing ponding Upstream.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-a	415519	108303	290	15.29	DS		Looking downstream towards riffle from bridge at upstream limit.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-b	415485	108299	300	15.37	RHB		Across river towards artificial bank and gravel deposit.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-c	415485	108299	70	15.42	US		US towards bridge and riffle.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-d	415468	108290	290	15.45	DS		DS to RHB.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-e	415441	108282	280	15.56	DS		DS Bar on left and riffle.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-f	415422	108282	280	15.56	DS		Tree overhanging channel.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-g	415421	108278	280	16.05	DS		Fallen tree.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-h	415401	108276	280	16.07	DS		DS towards riffle and meander.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-i	415353	108272	260	16.12	DS		DS bar in foreground steep RHB.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-j	415355	108272	275	16.16	DS		Point bar on RHB.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-k	415333	108279	330	16.20	RHB		Large fallen tree.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-I	415314	108268	10	16.25	RHB		Across river to fallen tree roots.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-m	415300	108260	240	16.31	DS		DS standard stretch.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-n	415269	108250	260	16.39	DS		Vegetated bar and riffle in distance.
14/07/2009	Dockens Water	DOR01	n/a	DOR0 -n2	415269	108250		16.59	US		Dry pool.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-0	415238	108238	260	17.04	DS		High bank.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-p	415231	108225	300	17.10	RHB		Collapsed bridge.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-q	415220	108218	220	17.15	DS		DS from collapsed bridge - straight section.
14/07/2009	Dockens Water	DOR01	n/a	DOR01-r	415147	108157	60	17.24	US		DS limit looking towards pipe crossing.

	Кеу
LHB	Left Hand Bank
RHB	Right Hand Bank
US	Upstream
DS	Downstream