


Agricultural Land Classification

HUMBLEBURN O.C.C.S.
 Subsoil Restoration Map
 and Soil Pit Location

FIELD No.	RESTORATION CONDITIONS
4a	Subsoil - 2 * 450mm Tipped
4b	Subsoil - Single Layer Tipped
5a	Subsoil - Single Layer Tipped
5b	Subsoil - 2 * 450mm Tipped
6	Subsoil - 2 * 450mm Tipped
7	Not Worked
8	Soil Storage Only

SOIL PIT	SOIL PIT NUMBER
■	Pit 1



Further details contained in MAFF (1988) Agricultural Land Classification of England and Wales - Revised guidelines and criteria for grading the quality of agricultural land. Maff (publications), London SE99 7TP. The information is accurate at base map scale but any enlargement would be misleading. Reproduction in whole or in part by any means is prohibited without the prior permission of MAFF.

Surveyed and drawn by the Resource Planning Team, ADAS Statutory Unit, Leeds.
 Based on the 1984 Ordnance Survey 1:10,000 map with the permission of the Controller of Her Majesty's Stationery Office. Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings. MAFF Licence No: GD272361
 Source map(s): NZ 25 SW
 Reference no: 69/96 © Crown Copyright Reserved 1996