

Tetbury, GloucesterSOIL PIT DESCRIPTION

<u>Topsoil</u>	0-23 cm FSZL 10YR43
<u>Subsoil 1</u>	23-44 cm FSZL/MCL 10YR54 Moderately Developed, Coarse Sub-angular Blocky Friable (= Moderate Structure) Porous (>0.5%, >0.5 mm)
<u>Subsoil 2</u>	44-120+ cm C 2.5Y54/64 (+Some weathering colours 7.5YR68) Very many distinct mottles (2.5Y62) Very Coarse Platy; at least very firm Degree of development not easy to assess (compacted/apedal) (= Poor Structure)
<u>ALC Wetness</u>	Gley from 44 cm SPL from 44 cm Wetness Class III; FCD = 197 days
Grade according to wetness (the most limiting factor) = 3A	