

NANCEMERE FARM, TRURO
SOIL PIT DESCRIPTION

Pit 1 MR - SW832462

Medium

Topsoil 0-15 cm

Heavy Clay Loam
10YR 4/3 brown
<1% stones 2-6 cm; 2% stones <2 cm

Subsoil 15-35 cm

Heavy Clay Loam
10YR 4/3 brown
2% stones 2-6 cm; 10% stones <2 cm
Weak, Fine subangular blocky structure
Friable
>0.5% biopores of >0.5 mm

Subsoil 2 35-60 cm

Clay
10 YR 5/6 yellowish brown
15% stones 2-6 cm; 15% stones <2 cm
Weak, fine Subangular blocky structure
Friable
>0.5% biopores of >0.5 mm

Subsoil 3 60 + cm

Fractured hard rock (*slate*)
10% soil in fractures

Denbigh Series